

### HELIDECK INSPECTION

# **CERTIFICATE**

## AMRUMBANK (EDYA)

### RWE RENEWABLES TRIDENT OFFSHORE GMBH

The above-mentioned helideck has been inspected according to legal national and international requirements (SOLF, AVV-HFP, EASA 965/2012, ICAO Annex 14 Vol. II and ICAO Heliport Manual) and, where applicable, to other national standards for offshore helidecks

The helideck has been found suitable for helicopter operations subject to below stated limitations, non-compliances and authorization by the approving authority. For more details see respective *Helideck Information Chart*.

#### HELIDECK INFORMATION

	TILLIDLOR IIVI ORIMITTIOIV	
D VALUE	POSITION	MTOW
23 m	N 54° 31' 11.69'' E 007° 44' 05.61''	12.8 t
,		\
	LIMITATIONS	
	TEMPORARILY VFR DAY ONLY	
	NON-COMPLIANCES	
\	NIL	
	10	
	SOPCIE	
	NEXT DUE	
	09.07.2025	
	LA ISO/IEC 12 UROPEALOS	,
23.06.2024		1. N A
Inspection date	Steffen Bechtel	Inspected by
	CYT 2001	